GSM-Support ul. Dobrego Pasterza 102/5, 31-416 Krak·w
mobile +48 608107455, NIP 8133358609 REGON: 181081334
www.gsm-support.net

Cruiser 2 Plus unlock DB2020 with USB key

Now possible unlock SonyEricsson W200/W300/W810 DB2012 !
Added FREE FLASHING for DB3150 platform (A2), DB2020 CID53 and PNX5230 CID53 - no logs, no internet connection required !
Added FREE unlock by patch for DB2020 CID52 - no logs, no internet connection required !
Unlock Z310 CID51 - 1 credit needed
Cruiser 2 Plus DB2020 unlock CRUISER is the first STANDALONE SOFTWARE for unlocking, **now also unlock db2020 models w/o patching**! changing language, changing customizations and repairing of new Sony Ericsson phones: K700i, K700c, K500i, K500c, K506c, K508i, K508c, F500i, S700i, S700c, S710a, Z1010i, Z1010c, V800, V802SE, J300, K300, Z800, K750, W800, K600, V600, new K700, new V800 and all old models, LG 3g, 8xxx series, Shrap, Siemens c62. Besides, CRUISER includes complete SE FIGHTER functionality.

GSM-SUPPORT has direct authorization from producer to sell this device.

Functions:

Read codes (supports also 16-digit long codes).
Read userlock.
cid 51 for unlock db2020 (1 log)
Flash main firmware part.
Change languagepack and software customization (db2020 - free).
Repair dead, blinking and "contact operator" phones.
Disable camera shutter sound.
Backup security zone.
Restore security zone.
Change phone type descriptor. - Reset air time, reset total call time, reset life time.
Reset joystick counter.
Enable/disable channel info, battery info, SIM toolkit support, SMS capability.
COMPLETE SE FIGHTER FUNCTIONALITY INCLUDED!

Prefered operating system is Windows XP

Supported models:

SonyEricsson - D750i, F500, J200i, J200c, J210i, J210c, J220c, J220a, J230i, J230c, J230a, J300i, J300c, J300a, K300i, K300c, K300a, K310i, K310c, K310a, K320i, K500i, K500c, K506, K508i, K508c, K510i, K510c, K510a, K550i, K550c, K600i, K600c, K608i, K610i, K610c, K610im, K618i, K618a, K700i, K700c, K750i, K750c, K758c, K790i, K790c, K790a, K800i, K800c, K810i, K818c, M600i M600c, M608c, P800, P802, P900, P907, P908, P910i, P910c, P990i, P990c, S700i, S700c, S710a, T610, T616, T618, T628, T630, T637, V600i, V630i, V800, V802se, W200i, W200c, W200a, W300i, W300c, W300a, W550i, W550c, W580i, W580c, W600i, W600c, W610i, W610c, W660i, W660c, W700i, W700c, W700a, W710i, W710c, W800i, W800c, W810i, W810c, W830i, W830c, W850i, W850c, W880i, W880c, W900i, W900c, W950i, W950c, W958c, Z200, Z208, Z300i, Z300c, Z300a, Z310i, Z310c, Z310a, Z500i, Z500c, Z500a, Z520i, Z520c, Z520a, Z525a, Z530i, Z530c, Z550i,

Z550c, Z550a, Z558i, Z558c, Z600, Z608, Z610i, Z610c, Z710i, Z710c, Z800i, Z800c, Z1010i, Z1010c
SonyEricsson W200/W300/W810 DB2012 - unlock by testpoint (requires open phone and use special UC-20 testpoint cable
SonyEricsson DB2020 CID53 - flashing without credits, no internet connection needed
SonyEricsson PNX5230 CID53 (W380, Z555) - flashing without credits, no internet connection needed
SonyEricsson DB3150 (A2) Flasher - K630, K850, V640, W910, Z750
SonyEricsson Calypso Flasher - J120, K200, K220
SonyEricsson Calypso Unlocker - K200, K220
SonyEricsson Locosto Flasher - T250, Z250, Z320
SonyEricsson Smartphones 2006 - M600, P1, P990, W950, W960
LG 3G - U8100, U8110, U8120, U8130, U8138, U8180, U8330, U8360, U8380, U8550.
Sharp 3G - V703SH, V801SH, V802SH, V902SH, V903SH, V550SH, V770SH, V804SH, GX-40, TQ-G400, TQ-G450,
Siemens - Supported C62 / C62c firmware versions are v25, v26, v27 and v28 (Only Unlock)
Ericsson OLD Models: A1018s, A1018sc, A1028s, A1028sc, A2618s, A2618sc, A2628s, A2628sc, A2638sc, A2668sc, A3618s, A3618sc, CA638, GA318, GA388, GA628, GF388, GF768, GF768c, GF788, GF788c, GF788e, GH388, GH398, GH688, GM518, GM618, GM718, I888 World, PA388, PF768, PH388, R190 setellite, R290 setellite, R250sPro, R310s, R310sc, R320s, R320sc, R320s TITAN, R380PDA, R380s, R380sc, R380e, R380World, R520m, R520mc, R600, R602, S868, SH888, T10s, T10sc, T18s, T18sc, T20s, T20sc, T20e, T20ec, T28s, T28sc, T28World, T28z, T29s, T29sc, T39m, T39mc, T62u, T65s, T66, T66c, T68i, T68ie, T68m, T68mc, T100, T102, T105, T106, T200, T202, T226, T226s, T230, T237, T238, T290i, T290c, T290a, T300, T302, T306, T310, T310c, T312, T316, T600, T602, TH688.
Supported are these CIDs: 16, 17, 19, 24, 27, 29, 36, 37, 41, 42, 49, 51 and 52. Unlock CID51 requires logs. DB2020 CID52 unlock by patch is FREE

NEW, UNLOCKING DB2020 !
K550, K550im, K610, K610im, K618, K790, K800, K810, V630, W610, W710, W830, W850, W880, W888, Z610, Z710

Set includes:
- protection card with reader
- access to producer's support
- warranty

É 2022 www.gsm-support.net