GSM-Support ul. Dobrego Pasterza 102/5, 31-416 Krak·w
mobile +48 608107455, NIP 8133358609 REGON: 181081334
www.gsm-support.net

Universal Box BB5 Test Point Adapter

Universal Box BB5 Test Point Adapter is a special adapter dedicated for Universal Box users which allows to unlock BB5 phones without any credits/logs for free.

Supported BB5 phone models and versions:

3109C - RM-274: V05.30, V05.50
3110C - RM-237: V04.91, V05.01, V05.50
3250 - RM-38: V04.21
3500C - RM-272: V05.51
3500Cb - RM-273: V05.51
5200 - RM-174: V03.70-ATB, V3.70-ATD, V3.92-ATB, V3.92-ATD, V03.93-ATB, V03.93-ATD, V04.71-ATB, V04.71-ATD, V05.00-ATB, V05.00-ATD, V05.51-ATB, V05.51-ATD
5200B - RM-181: V03.70-ATB, V3.70-ATD, V3.92-ATB, V3.92-ATD, V03.93-ATB, V03.93-ATD, V04.71-ATB, V04.71-ATD, V05.00-ATB, V05.00-ATD, V05.51-ATB, V05.51-ATD
5300 - RM-146: V03.50-ATB, V03.50-ATD, V03.51-ATB, V03.51-ATD, V03.92-ATB, V03.92-ATD, V03.93-ATB, V03.93-ATD, V04.51-ATB, V04.51-ATD, V04.70-ATB, V04.70-ATD, V4.71-ATB, V4.71-ATD, V05.00-ATB, V05.00-ATD, V05.02-ATB, V05.02-ATD, V05.5.50-ATB, V05.5.50-ATD, V05.51-ATB, V05.51-ATD
5300B - RM-147: V03.50-ATB, V03.50-ATD, V03.51-ATB, V03.51-ATD, V03.92-ATB, V03.92-ATD, V03.93-ATB, V03.93-ATD, V04.51-ATB, V04.51-ATD, V04.70-ATB, V04.70-ATD, V4.71-ATB, V4.71-ATD, V05.00-ATB, V05.00-ATD, V05.02-ATB, V05.02-ATD, V05.5.50-ATB, V05.5.50-ATD, V05.51-ATB, V05.51-ATD
5500 - RM-86: V03.55
6085 - RM-198: V03.52-NDO, V03.52-PDO, V03.70-NDO, V03.70-PDO, V03.71-NDO, V03.71-PDO, V04.11-NDO, V04.11-PDO, V04.22-NDO, V04.22-PDO, V04.26-NDO, V04.26-PDO, V04.29-NDO, V04.29-PDO, V04.30-NDO, V04.30-PDO, V05.02-NDO, V05.02-PDO, V05.03-NDO, V05.03-PDO
6086 - RM-188: V3.51, V03.52, V05.03, V13.51, V15.02, V15.04
6086B - RM-260: V3.51, V03.52, V05.03, V13.51, V15.02, V15.04
6125 - RM-178: V03.51-ATB, V03.71-ATB, V03.72-ATB, V04.20-ATB, V04.20-ATD, V05.43-ATB, V05-43-ATD
6126 - RM-126: V04.24, V05.61
6131 - RM-115: V05.50, V06.10
6136 - RM-199: V03.71.2, V04.01, V14.01, V05.21, V15.21
6151 - RM-200: V03.91, V04.10
6233 - RM-145: V03.70-SPN, V04.52-SPN, V04.54-SPN, V04.91-SPN, V05.10-ETM, V05.10-SPN
6234 - RM-123: V03.70-SPN, V04.52-SPN, V04.54-SPN, V04.91-SPN, V05.10-ETM, V05.10-SPN0
6280 - RM-78: V03.36-ETA_AD1, V03.36-SPN_AD1, V3.36-ETA_AD0, V03.36-SPN_AD0, V03.40-ETA_AD1, V03.40-SPN_AD1, V3.40-ETA_AD0, V3.40-SPN_AD0, V03.41-ETA_AD1, V03.41-SPN_AD1, V03.41-ETA_AD0, V03.41-SPN_AD0, V03.60-ETA_AD1, V03.60-SPN_AD1, V03.60-ETA_AD0, V03.60-SPN_AD0, V03.65-ETA_AD1, V03.65-SPN_AD1, V03.65-ETA_AD0, V03.65-SPN_AD0, V03.70-ETA_AD1, V03.70-SPN_AD1, V03.70-ETA_AD0, V03.70-SPN_AD0, V03.81-ETA_AD1, V03.81-SPN_AD1, V03.81-ETA_AD0, V03.81-SPN_AD0, V05.92-ETA_AD1, V05.92-SPN_AD1, V05.92-ETA_AD0, V05.92-SPN_AD0, V05.94-ETA_AD1, V05.94-SPN_AD1, V05.94-ETA_AD0, V05.94-SPN_AD0, V05.96-ETA_AD1, V05.96-SPN_AD1, V05.96-ETA_AD0, V05.96-SPN_AD0, V06.10-ETA_AD1, V06.10-SPN_AD1, V06.10-ETA_AD0, V06.10-SPN_AD0, V06.43-ETA_AD1, V06.43-SPN_AD1, V06.43-ETA_AD0, V06.43-SPN_AD0
6300 - RM-217: V04.20-ATB, V04.20-ATD, V04.20-SPN, V04.70-ATB, V04.70-ATD, V04.70-SPN, V04.71-ATB, V04.71-ATD,

V04.71-SPN, V05.00-ATB, V05.00-ATD, V05.00-SPN, V05.50-ATB, V05.50-ATD, V05.50-SPN, V05.52-ATB, V05.52-ATD, V05.52-SPN, V06.01-ATB, V06.01-ATD, V06.01-SPN
6300B - RM-222: V04.20-ATB, V04.20-ATD, V04.20-SPN, V04.70-ATB, V04.70-ATD, V04.70-SPN, V04.71-ATB, V04.71-ATD, V04.71-SPN, V05.00-ATB, V05.00-ATD, V05.00-SPN, V05.50-ATB, V05.50-ATD, V05.50-SPN, V05.52-ATB, V05.52-ATD, V05.52-SPN, V06.01-ATB, V06.01-ATD, V06.01-SPN
7370 - RM-70: V04.13
7373 - RM-209: V03.90, V04.70, V04.71, V05.00, V05.50
7390 - RM-140: V03.84, V04.51
8600 - RM-164: V03.52
E50-1 - RM-170: V2.26.01, V3.37.23, V4.41.41
E50-2 - RM-171: V2.26.01, V3.37.23, V4.41.41
E50-3 - RM-172: V2.26.01, V3.37.23, V4.41.41
E60 - RM-89: V1.0533.47.12, V2.0533.47.5, V3.0533.6
E61 - RM-89: V1.0533.47.14, V2.0533.47.5, V3.0533.6
E61i - RM-227: V1.0615.31, V2.0615.11
E62 - RM-88: Vp2.0618.06.17, V3.06.33.09.11
E65 - RM-208: V1.0615.25, V1.0615.25.1, V2.0615.10, V2.0615.30
N71-1 - RM-67: V05wk33v23.5
N73-1 - RM-133: V05wk47v28.1, V05wk47v28.3, V05wk47v32.1, V05wk47v34.1, V05wk47v38, V05wk47v38.1, V05wk47v38.2, V05wk47v46.3, V05wk47v48, V05wk47v48.3, V05wk47v50.3, V05wk47v50.5, V05wk47v51.3, V05wk47v51.4, V05wk47v51.5, V05wk47v51.7
N73-5 - RM-132: V05wk47v28.3, V05wk47v34.1, V05wk47v38, V05wk47v38.2, V05wk47v48
N75 - RM-128: V06wk15v37
N77 - RM-194: V06wk15v41, V06wk15v47
N80 - RM-92: V05wk33v29, V05wk33v29.2, V05wk33v33.1, V05wk33v33.2, V05wk33v40, V05wk33v42, V05wk33v46
N91 - RM-91: V05wk33v29, V05wk33v29.2, V05wk33v33.1, V05wk33v33.2, V05wk33v40, V05wk33v42
N91 - RM-43: Vw3306w12v1, Vw3306w16v2, Vw3306w24v2, Vw3306w24v4, Vw3306w38v1, Vw3306w47v1, Vw3307w11v1
N91-5 - RM-158: Vw3306w12v1, Vw3306w16v2, Vw3306w24v2, Vw3306w24v4
N92 - RM-100: V05wk47v41.1, V05wk47v54
N93 - RM-55: V05wk47v28.2, V05wk47v35.1
N95 - RM-159: V06wk41v18.4, V06wk41v23.4, V06wk41v31, V06wk41v31.1, V06wk41v43.1
N95B - RM-160: V06wk41v38, V06wk41v42

É 2022 www.gsm-support.net