

Product	2.0.7.0	2.0.7.1	2.0.7.2	2.0.8.0	2.0.8.2	2.0.8.3	2.0.8.5	ASIC Id / Method	Flash File Pack
1112b								012x,102x,113x,1201,214x,2201,203x	ASIC 2 / 32 NOR
RH-92 v5.01		+						Temporary Patch	dp 00 24
RH-92 v5.03	+								dp 00 31
RH-92 v5.55		+							dp 04 51
RH-92 v6.00		+							dp 07 03
1110i / 1112								012x,102x,113x,1201,214x2201,203x	ASIC 2 / 32 NOR
RH-93 v5.03	+							Temporary Patch	dp 00 21
RH-93 v5.04	+								dp 00 30
RH-93 v5.50	+								dp 01 00
RH-93 v5.53	+								dp 03 00
RH-93 v5.54	+								dp 04 00
RH-93 v6.00	+								dp 07 01
RH-93 v6.01	+								dp 08 00
RH-93 v6.40	+								dp 10 01
RH-93 v6.41	+								dp 10 10
RH-93 v6.46								Permanent Patch [INCOMPATIBLE SW]	dp 10 10
RH-93 v6.93		+						Temporary Patch	dp 14 01
RH-93 v7.02		+						Temporary Patch	dp 15 00
1112								2292	ASIC 11 / 32 NOR
RH-94 v3.00	+							Temporary Patch	dp 02 12
RH-94 v3.11	+								dp 04 00
RH-94 v3.30									dp 06 00
1112i								2292	ASIC 11 / 32 NOR
RH-95								no File	
1200								2292	ASIC 11 / 32 NOR
RH-99 v3.12		+						Permanent Patch	dp 06 00
RH-99 v3.40		+							dp 11 00
RH-99 v3.44		+							dp 13 00
RH-99 v4.00		+							dp 24 00
RH-99 v4.11		+							dp 25 00
RH-99 v4.15									
RH-99 v4.51		+							dp 27 00
RH-99 v5.06		+							dp 28 00
RH-99 v5.23		+							dp 29 00
RH-99 v5.51				+					dp 33 00
RH-99 v5.53				+					dp 34 00
RH-99 v5.71					+				dp 35 00
RH-99 v5.80					+				dp 36 00
RH-99 v5.91							+		dp 37 00
1200b								2292	ASIC 11 / 32 NOR
RH-100 v4.00									
RH-100 v4.11									
RH-100 v5.06			+						dp 28 00
RH-100 v5.32				+					dp 32 00
RH-100 v5.80									dp 36 00
1202-2 / 1203-2								2293 - Currently not Supported	
RH-112 v2.80					+			Permanent Patch	dp 02 00
RH-112 v3.00						+			dp 03 00
RH-112 v3.10						+			dp 04 00
1208 / 1209								2292	ASIC 11 / 32 NOR
RH-105 v3.72		+						Permanent Patch	dp 18 00
RH-105 v4.00		+							dp 24 00
RH-105 v4.11		+							dp 25 00
RH-105 v4.51		+							dp 27 00
RH-105 v5.06		+							dp 28 00
RH-105 v5.23		+							dp 29 00
RH-105 v5.51				+					dp 33 00
RH-105 v5.53				+					dp 34 00
RH-105 v5.71					+				dp 35 00
RH-105 v5.80					+				dp 36 00
RH-105 v5.91							+		dp 37 00
1208b								2292	ASIC 11 / 32 NOR
RH-106 v4.00				+				Permanent Patch	dp 24 10
RH-106 v4.11				+					dp 25 10
RH-106 v5.06		+							dp 28 00
RH-106 v5.23				+					dp 29 00
RH-106 v5.32				+					dp 32 00
RH-106 v5.80							+		dp 36 00
1650								2292	ASIC 11 / 128 NOR
RM-305 v4.11		+						Permanent Patch	dp 25 00
RM-305 v4.51		+							dp 27 00
RM-305 v5.06		+							dp 28 00
RM-305 v5.23		+							dp 29 00
RM-305 v5.30		+							dp 30 00
RM-305 v5.32				+					dp 32 00
RM-305 v5.51				+					dp 33 00
RM-305 v5.53				+					dp 34 00
RM-305 v5.71					+				dp 35 00
RM-305 v5.80					+				dp 36 00
RM-305 v5.91							+		dp 37 00
1650b								2292	ASIC 11 / 128 NOR
RM-306								no File	
1661-2b								2293 - Currently not Supported	ASIC 11 / 128 NOR
RH-121 v3.10									dp 01 02
1661-2								2293 - Currently not Supported	ASIC 11 / 128 NOR
RH-122 v3.10						+			dp 01 10
RH-122 v3.36									dp 02 00
RH-122 v3.70									dp 03 00

1680c-2								3160,3161, 3162 ,3164,3166	ASIC 11 / 256 NOR
RM-394 v5.61				+				Permanent Patch 2	dp 00 34
RM-394 v5.63				+					dp 00 58
RM-394 v6.82									dp 04 00
1680c-2b								3160,3161,3162,3164,3166	ASIC 11 / 256 NOR
RM-395 v5.61				+				Permanent Patch 2	dp 00 34
RM-395 v6.82									dp 04 00
1681c								3160,3161,3162,3164,3166	ASIC 11 / 256 NOR
RH-118 v5.61				+				Permanent Patch 2	dp 00 41
2310								012x,102x,113x,1201,214x, 2201 ,203x	ASIC 2 / 32 NOR
RM-189 v2.10	+							Temporary Patch	
RM-189 v3.00	+								dp 02 10
RM-189 v3.10	+								dp 02 31
RM-189 v3.21	+								dp 03 00
RM-189 v3.31	+								dp 05 00
RM-189 v5.10	+								dp 06 01
RM-189 v5.90		+							dp 09 00
RM-189 v6.30		+							dp 12 50
RM-189 v6.33		+							dp 13 00
RM-189 v6.50		+							dp 14 00
RM-189 v6.52		+							dp 15 00
2310b								012x,102x,113x,1201,214x,2201,203x	ASIC 2 / 32 NOR
RM-190								no File	
2323c-2								3160,3161,3162,3164,3166, 3168	
RM-543 v6.75									dp 10.0
2330c-2								3160,3161,3162,3164,3166, 3168	ASIC 11 / 256 NOR
RM-512 v6.46									dp 5.0
RM-512 v6.75									dp 6.0
2600c-2								3160,3161, 3162 ,3164,3166	ASIC 11 / 256 NOR
RM-340 v5.21		+						Permanent Patch 2	dp 01 09
RM-340 v5.22		+							dp 02 02
RM-340 v5.61			+						dp 00 23
RM-340 v6.82									dp 02 61
2600c-2b								3160,3161,3162,3164,3166	ASIC 11 / 256 NOR
RM-341 v4.61								no File	
2610								3040	ASIC 11 / 128 NOR
RH-86 v3.53	+							Temporary Patch	dp 60 00
RH-86 v3.71	+								dp 71 00
RH-86 v3.75	+								dp 74 00
RH-86 v3.77	+								dp 79 00
RH-86 v4.50	+								dp 128 00
RH-86 v4.51	+								dp 117 00
RH-86 v4.90	+								dp 138 00
RH-86 v5.65								[INCOMPATIBLE SW]	
RH-86 v5.90		+						Temporary Patch	dp 167 00
RH-86 v6.70		+						Temporary Patch	dp 190 00
RH-86 v6.73				+				Temporary Patch	dp 196 00
RH-86 v6.80								[INCOMPATIBLE SW]	
RH-86 V7.10				+					dp 197 00
RH-86 V7.11						+			dp 204 00
2610b								3040	ASIC 11 / 128 NOR
RH-87 v3.53	+							Temporary Patch	dp 60 00
RH-87 v3.71	+								dp 71 00
RH-87 v3.75	+								dp 74 00
RH-87 v3.77	+								dp 79 00
RH-87 v4.50	+								dp 128 00
RH-87 v4.51	+								dp 117 00
RH-87 v4.90	+								dp 138 00
RH-87 v5.65								[INCOMPATIBLE SW]	dp 106 00
RH-87 v5.90		+						Temporary Patch	dp 167 00
RH-87 v6.70		+						Temporary Patch	dp 190 00
RH-87 v6.73				+				Temporary Patch	dp 196 00
RH-87 v6.80								[INCOMPATIBLE SW]	dp 108 00
RH-87 V7.04a								not Supported ASIC 3168	
RH-87 V7.10				+					dp 197 00
RH-87 V7.11						+			dp 204 00
2626								3040	ASIC 11 / 128 NOR
RM-291 v3.51	+							Temporary Patch	dp 17 00
RM-291 v4.61		+							dp 34 00
RM-291 v6.80		+							dp 42 00
2630								3160,3161, 3162 ,3164,3166	ASIC 11 / 256 NOR
RM-298 v3.82		+						Permanent Patch 2	dp 04 00
RM-298 v4.20		+							dp 07 07
RM-298 v4.21		+							dp 09 04
RM-298 v4.90		+							dp 10 00
RM-298 v5.20		+							dp 10 13
RM-298 v5.22		+							dp 10 19
RM-298 v5.61				+					dp 10 40
RM-298 v5.62				+					dp 10 49
RM-298 v6.82									dp 11 71
RM-298 v57.20									dp 02 00
2630b								3160,3161,3162,3164,3166	ASIC 11 / 256 NOR
RM-299 v4.20		+						Permanent Patch 2	dp 05 26
RM-299 v5.61				+					dp 11 02

RM-299 v5.62					+						dp 11_06
2660									3160,3161,3162,3164,3166		ASIC 11 / 128 NOR
RM-292 v3.63											dp 13_00
RM-292 v5.20											dp 15_06
RM-292 v5.61											dp 15_28
RM-292 v5.62											dp 15_40
RM-292 v5.66											
RM-292 v6.82											
2660b									3160,3161,3162,3164,3166		ASIC 11 / 128 NOR
RM-293 v3.63											dp 05_10
RM-293 v5.20											
RM-293 v5.62											dp 06_03
2680s-2									3160,3161,3162,3164,3166		ASIC 11 / 256 NOR
RM-392 v4.56							+				dp 20_3.04
RM-392 v4.91							+				dp 20_4.00
RM-392 v5.28											dp 20_4.99
RM-392 v6.17											dp 50_00
2680s-2b									3160,3161,3162,3164,3166		ASIC 11 / 256 NOR
RM-393 v4.56							+				dp 20_3.04
RM-393 v4.91							+				dp 20_4.00
RM-393 v5.28											dp 20_4.99
2760									3160,3161,3162,3164,3166		ASIC 11 / 256 NOR
RM-258 v3.62		+							Permanent Patch 2		dp 09_00
RM-258 v4.20				+							
RM-258 v4.22		+									dp 10_21
RM-258 v5.20		+									dp 11_06
RM-258 v5.22		+									dp 11_13
RM-258 v5.61					+						dp 11_31
RM-258 v5.62					+						dp 11_43
RM-258 v6.82											dp 11_65
RM-258 v7.60											dp 15_00
2760b									3160,3161,3162,3164,3166		ASIC 11 / 256 NOR
RM-259 v3.62		+							Permanent Patch 2		dp 02_25
RM-259 v4.20					+						dp 02_21
RM-259 v5.20					+						dp 03_11
RM-259 v5.62					+						dp 03_13
2760h									3160,3161,3162,3164,3166		ASIC 11 / 256 NOR
RM-391 v5.45					+				Permanent Patch 2		dp 00_52
5000d-2									3160,3161,3162,3164,3166		ASIC 11 / 256 NOR
RM-362 v3.50							+		Permanent Patch 2		dp 20_3.00
RM-362 v4.60									no Radio		dp 20_3.00
RM-362 v4.88											dp 20_3.30
RM-362 v4.89											dp 20_4.00
RM-362 v5.27											dp 20_5.00
RM-362 v5.45											dp 20_7.00
RM-362 v6.31											dp 50_00
5000d-2b									3160,3161,3162,3164,3166		ASIC 11 / 256 NOR
RM-363 v3.50							+		Permanent Patch 2		dp 20_3.00
RM-363 v3.54							+				dp 20_3.02
5030c-2									2293		ASIC 11 / 128 NOR
RM-524 v3.75											dp 01_01
6030b									012x,102x,113x,1201,214x,2201,203x		ASIC 2 / 128 NOR
RM-225 v5.24	+								Temporary Patch		dp 54_00
RM-225 v5.25	+										dp 55_00
RM-225 v5.27											dp 60_00
6060v									3040		ASIC 11 / 128 NOR
RH-97 v3.01	+								Temporary Patch		dp 12_00
RH-97 v3.03	+										dp 20_00
6061									3040		ASIC 11 / 128 NOR
RH-98 v3.01	+								Temporary Patch		dp 12_00
RH-98 v3.03	+										dp 20_00
7070d-2									3160,3161,3162,3164,3166		ASIC 11 / 256 NOR
RH-116 v6.20							+		Permanent Patch 2		dp 00_53
RH-116 v6.35									no Radio		dp 01_07
RH-116 v6.82											dp 02_07
7070d-2b									3160,3161,3162,3164,3166		ASIC 11 / 256 NOR
RH-117									no File		
7100s-2									3160,3161,3162,3164,3166,3168		ASIC 11 / 256 NOR
RM-438 v5.22											dp 7_0
RM-438 v5.41											dp 8_0
RM-438 v6.31											dp 9_0
7100s-2b											
RM-439									no File		